




PURRINGTON LOOMS, LLC

P. O. Box 44, Scott Depot, WV 25560-0044

304-743-5455

www.purringtonlooms.com


USING YOUR RADDLE OR REED FEET



When using your Raddle or Reed Feet, you can set them on a table or you can clamp them to any work surface.

Insert pegs in the appropriate holes to give you the spacing you need to set between the pegs whatever it is you are trying to hold. You may be able to vary slightly the spacing by rotating the peg in the hole.

Reed or Raddle Feet



Space between pegs in holes:

1-2 5/8"

1-3 1 1/8"

1-4 1 5/8"